

## Share Knowledge ~ Save a Life

#### **ZERO FATALITIES**



# **SOFA ALERT**

### PLEASE POST IMMEDIATLY



July 7, 2024, Melrose Park, IL – While shoving into a track a Conductor was riding the leading end of a tank car and was fatally injured after colliding with a train on the lead track.

#### Take-Away

While this recent case has not yet been analyzed, the SOFA Working Group reminds all employees to remain vigilant during switching operations by not only protecting shove movements, but also protecting themselves by avoiding close or no clearances hazards. Inexperienced employees should always be mentored when possible. Last, but not least, stop the movement in instances of uncertainty and remember to always hold a job briefing whenever the job or situation changes.

## Most Common Findings in Switching Operations Fatalities

Close / No Clearance Inexperienced Employee Industry Hazard Inadequate Job Briefing Struck by Mainline Train

25%

22%

21%

20%

17%